## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicants : K. SONOBE, et al. Certificate of Correction Branch

For : POLYACETAL RESIN COMPOSITION

## REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
U.S. Patent and Trademark Office
Customer Service Window, Mail Stop Certificate of Correction Branch
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Sir:

Please find attached a proposed Certificate of Correction.

Please correct the following error appearing in the printed patent, which is apparently the fault of the U.S. Patent and Trademark Office. Thus, no fee is required to be paid to correct this error.

On the cover page, under Abstract (line 8) of the printed patent, "0.00.5" should be --0.005--. This appeared correctly on page 79, line 11 (Abstract) filed on July 20, 2006.

Therefore, it is respectfully requested that a Certificate of Correction issue in the aboveidentified patent as follows:

On the cover page, under Abstract, line 8 of the printed patent, change "0.00.5" to -- 0.005--.

1

Should there be any questions, the Examiner is invited to contact the undersigned at the below-listed number.

Respectfully submitted, K. SONOBE et al.

Reg. No. 29,027 Arnold Turk

Reg. No. 33094

June 1, 2010 GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191 (703) 716-1191